









- ### Airport Q1 Inspection Repairs
- 1) Culvert at Linden and Aviation- clean and stabilize with cobbles
 - 2) Box NE of runway – repair
 - 3) AP-08 channel – clean out sediment, stabilize surrounding area with millings/cobble
 - 4) Silverhawk Parking Area – place millings on unpaved parking area
 - 5) AP-06 – clean inlet and trim around it
 - 6) Pile of post holes on Aviation – dispose or take to the pit
 - 7) AP-04 – stabilize parking area near SW pond with millings, stabilize banks with cobble
 - 8) AP-03 – clean off manhole lid
 - 9) AP-02 – remove weeds at overflow box, stabilize slopes along Aviation with cobble

Legend

| | |
|--|---|
|  Rivers |  Q1 Inspection Areas to Repair |
|  Surface Waters |  Direct Discharge Outfalls |
|  Storm Drain Lines |  Pond Outfalls |

