



**Analytical  
Laboratories  
Inc**

## Analytical Laboratories, Inc.

1804 N. 33rd Street  
Boise, Idaho 83703  
Phone (208) 342-5515

### Laboratory Analysis Report

Sample Number: 1746203

**Attn:** SALVADOR ARREOLA  
CALDWELL WASTEWATER  
PO BOX 1179  
CALDWELL, ID 83607

**Collected By:** R. HAWKER  
**Submitted By:** B. MILLER

**Source of Sample:**

INSPIRE

**Time of Collection:** 16:20:00  
**Date of Collection:** 10/3/2017  
**Date Received:** 10/4/2017  
**Report Date:** 10/16/2017

**PWS:**

Field PH: Lab PH:  
Field Temp: Temp in Lab: 5.2

Test Requested	MCL	Result	Units	MDL	Method	Completed	Analyst
Arsenic Low	0.01	3.5	ug/L	0.5	EPA 200.8	10/13/2017	JH
Cadmium Low	0.005	<0.25	ug/L	0.25	EPA 200.8	10/13/2017	JH
Chromium Low	0.1	19	ug/L	1	EPA 200.8	10/13/2017	JH
Copper Low		50	ug/L	2	EPA 200.8	10/13/2017	JH
Lead Low	0.015	171	ug/L	0.5	EPA 200.8	10/13/2017	JH
Mercury, Hg	0.002	<0.2	ug/L	0.2	EPA 245.1	10/5/2017	JD
Metals Digestion		*			EPA 200.2	10/4/2017	JD
Nickel Low		11.6	ug/L	0.5	EPA 200.8	10/13/2017	JH
Silver Low		<0.2	ug/L	0.2	EPA 200.8	10/13/2017	JH
Zinc, Zn	UR	27	ug/L	2	EPA 200.7	10/5/2017	JMS
Cyanide, Total	0.20	<0.005	mg/L	0.005	EPA 335.4	10/11/2017	DS
Biochemical Oxygen		*	mg/L	3	SM 5210 B	10/9/2017	GM

\*BOD invalid, dissolved oxygen level considerably higher after five days of incubation, suspect matrix interference.

# PRELIMINARY

Thank you for choosing Analytical Laboratories for your testing needs.

If you have any questions concerning this report,  
please contact: **James Hibbs**